

IALA COUNCIL
62nd session



21-24 June 2016
Lisbon
Portugal

11 – TECHNICAL ACTIVITIES

11.2 – ENG

Draft IALA Guideline 1041 Ed.3.0
Sector Lights

Note by the Secretariat

1. BACKGROUND

This is a revision of Guideline 1041 of December 2008 finalized at ENG4.

This is a major update of the Guideline with the addition of a section on theodolite alignment of sector lights.

The format has been updated to the new IALA style with the addition of a section for acronyms and amendment of the definition section.

Equations have been reviewed and titles added.

The finalized document is submitted as input paper C62-11.2.19.

2. THE COUNCIL IS REQUESTED TO

Approve the Guideline 1041 – Sector Lights revised to its edition 3.0.